

Site Plan Notes Varda Residence

1918 West Cedar Lake Parkway

- All dashed contour lines are existing. Solid lines are
- proposed.

 For existing conditions refer to certified survey dated July 23, 2013,

 Existing house and garage to be demolished and removed.

 Locate new house on property by setting southeast corner of living roam deck at settank line. North façade to be 60° south of north property line. New detected garage to be 60° west of new attached garage and 1'6" south of north property line.

- Keyed Notes:

 1. Planting bed along new garage
 2. Trench drain with steel grating set in concrete apron along
 2. Trench drain with steel grating set in concrete apron along
 3. 60° high soild wood fence and gate,
 4. 60° high soild wood fence and gate,
 5. 80° high stone wall with soild wood gate. See elevations,
 6. Concrete paver walk and patio,
 7. Line of second floor roof edge.
 8. Concrete walk/steps to side entry, 6° risers and 12" treads,
 9. Projecting bay for lower level gas fireplace,
 10. New concrete stoop at lower level siding door, Stoop fills area under north end of deck. Elev 775.4 at door, Slope 2%,
 11. New wood deck at elev, 884.4,
 12. Wood steps down to lower deck. 5 risers at 6°. 12" treads,
 Footlights centered in each riser.
- 13. Wood lower deck at elev. 883.9. Grade at foundation wall under decks is 880.0.
 14. Wood steps down lawn. 5 risers at 6". 12" treads. Footlights


- centered in each riser.

 15.Edge of second floor balcony.

 16. Planter with wood chip mulch.

 17. Stucco wall with cast stone cap.

 18. Front yard setback line established as
- as line between front
- Glass guardrail at deck edge.
 Extend planter wall under deck to foundation wall.
 Detted line is outline of existing structure to be removed.
 Existing tree to remain protect from damage during construction.
- Concrete paver front walk with concrete steps down to existing grade at property line.
 At Repair existing stone steps and walk down slope and to
- area in determining FAR. The house floor elevations have been set to meet this requirement. First floor is at 884.5 and the basement floor is 975.5. The point 4 feet below the first floor elevation is 880.5. The dashed line along the perimeter of the west side of the house indicates the area where normal grade is above 880 fs." The length of this portion of the perimeter is 108. The remaining portion of the perimeter, where normal grade is below 880 fs.", is 95 in length. Based on this design, the floor area of the basement has not been included in the total house floor area for calculation of FAR. 25.EAR calculations. At a plane that is 4 feet below the first floor, at least 50% of the house perimeter must be below the normal grade in order for the floor area of the basement to be excluded from total house floor



4 feet high, BB Hetz Midget White Cedar Thuja Occidentalis 'Hetz Midget' 18" high, BB


Aussian Cypness Microbiata Decussata
Aussian Cypness Microbiata Decussata
Auf spreach, Marymus Euonymus Alakus
Arrigel Boyymus Euonymus Alakus
Arrigel Boywood Cornus Sericea 'Cardinal'
3 It high, B
Francee Hosta Hosta Francee

1920


Ŧ 8 유


Guacamole Hosta Hosta 'Guacomole'

rich Fern Matteuccia Strutheriopteris





1918 STAR LAKE PKWY VARDA RESIDENCE





1918 CEDAR LIKE PRING





PLEASE COORDINATE WITH SITE PLAN TO MEASURE EXIST (NORMAL) GRADE AT HOUSE PERIMETER

15

